




1. FILL TANK WITH 100 GAL. OF WATER




2. TURN PUMP ON FOR MIXING




3. ADD (3) BOXES OF WHITE PAINT




4. MIX WHILE SPRAYING WHITE PAINT ON ICE SURFACE



5. ELEVATE TANK TO SPRAY ALL REMAINING PAINT



6. SHUT OFF PUMP. REPEAT STEPS 1 - 5 FOR 2ND & 3RD COAT OF ICE PAINT



ULTRA PURE
premium ice paints & coatings
MIXING & APPLICATION GUIDE